




Macon-Bibb County Guardrail Information							1
Location:	Williamson Road at Brad Walsh Pkwy						
	Demo rail:		Demo Post:	End Anchor:			
Length of new W rail:	112.5	Post at:		Curved Rail:	Radius:		
Straighten rail:				Reset Posts:	Blocks:		
New Posts:			Type 12A Anchor:	1	Type 1	1	
New Absorber end:							
Mobilization:	1	LS					
Misc Cost:		LS	Handrail				
Reflectors Needed:		(Y/N)					
Statement of Needs							
Remove and replace entire section of rail.							
							
Comments:							
Estimated Cost:							
Macon-Bibb County Guardrail Information							2
Location:	Foster Rd at Central City Church.						
	Demo rail:		Demo Post:	End Anchor:			
Length of new W rail:	262.5	Post at:		Curved Rail:	Radius:		
Straighten rail:				Reset Posts:	Blocks:		
New Posts:			Type 12A Anchor:	1	Type 1	1	
New Absorber end:							
Mobilization:	1	LS					
Misc Cost:		LS					
Reflectors Needed:		(Y/N)					
Statement of Needs							
NOT WARRANTED - REMOVED							
							
Comments:							
Estimated Cost:							
Macon-Bibb County Guardrail Information							3
Location:	Jeffersonville Rd at RR overpass, NW Intersection.						
	Demo rail:		Demo Post:	End Anchor:			
Length of new rail:		Post at:		Curved Rail:	Radius:		
Straighten rail:				Reset Posts:	Blocks:		
New Posts:			Type 12A Anchor:	1	Type 1		
New Absorber end:							
Mobilization:	1	LS					
Misc Cost:	1	LS					
Reflectors Needed:		(Y/N)					
Statement of Needs							
21' of T beam, 12.5' of W beam. Misc Cost due to extra daily operation costs/flagging, due to narrow shoulder.							
							
Comments:							
Estimated Cost:							

Macon-Bibb County Guardrail Information						4
Location:	2881 Ingleside Ave., between Candler Dr and Ashley Place.					
	Demo rail:		Demo Post:	End Anchor:		
Length of new W rail:	500		Post at:	Curved Rail:	Radius:	
	Straighten rail:			Reset Posts:	Blocks:	
	New Posts:			Type 12A Anchor:	1	Type 1 1
New Absorber end:						
	Mobilization:	1	LS			
	Misc Cost:	1	LS			
	Reflectors Needed:		(Y/N)			
Statement of Needs						
New W beam guardrail. Public Works to remove and replace existing R/R iron posts in concrete and single steel cable wire fence. Misc. cost due to flagging being required (narrow shoulder). 6' posts required.						
Comments:						
	COST:					



Macon-Bibb County Guardrail Information						5
Location:	Hartley Bridge Rd @ Echeconnee Crk. 850' east of County Line, North side of road.					
	Demo rail:		Demo Post:	End Anchor:		
Length of new rail:			Post at:	Curved Rail:	Radius:	
	Straighten rail:			Reset Posts:	Blocks:	
	New Posts:			Type 12A Anchor:	1	Type 1
New Absorber end:						
	Mobilization:	1	LS			
	Misc Cost:	1	LS			
	Reflectors Needed:		(Y/N)			
Statement of Needs						
Replace damaged 12A end with 12A, 25' of W rail, transition to 31" tall. Misc. cost due to daily flagging operation, due to narrow shoulder.						
Comments:						
	COST:					



Macon-Bibb County Guardrail Information						6
Location:	Columbus Rd @ I-475, NW bridge corner.					
	Demo rail:			End Anchor:		
Length of new W rail:	62.5		Post at:	Curved Rail:	Radius:	
	Straighten rail:			Reset Posts:	Blocks:	
	New Posts:			Type 12A Anchor:	Type 1	1
New Absorber end:						
	Mobilization:	1	LS			
	Misc Cost:	1	LS			
	Reflectors Needed:		(Y/N)			
Statement of Needs						
Replace Type 1 end section. 62.5' feet of new W Beam. Misc cost, due to flagging requirement, due to bridge sight distance.						
Comments:						
	COST:					



Macon-Bibb County Guardrail Information						7
Location:	Rivoli Drive, near 215 Abington Ct.					
Demo rail:		Demo Post:		End Anchor:		
Length of new rail:	500	Post at:		Curved Rail:		Radius:
Straighten rail:				Reset Posts:		Blocks:
New Posts:				Type 12A Anchor:	1	End Piece 1
New Absorber end:						
Mobilization:	1	LS				
Misc Cost:		LS				
Reflectors Needed:		(Y/N)				
Statement of Needs						
NOT WARRANTED - REMOVED						
Comments:						
COST:						





Macon-Bibb County Guardrail Information						8
Location:	7761 Nowell Road South, at curve.					
Demo rail:		Demo Post:		End Anchor:		
Length of new rail:		Post at:		Curved Rail:		Radius:
Straighten rail:				Reset Posts:		Blocks:
New Posts:				Type 12A Anchor:		Type 1
New Absorber end:						
Mobilization:		LS				
Misc Cost:		LS				
Reflectors Needed:		(Y/N)				
Statement of Needs						
NOT WARRANTED - REMOVED						
Comments:	NEED CHEVRONS AND SIGNAGE					
COST:						




Macon-Bibb County Guardrail Information						9
Location:	Log Cabin Rd Bridge over Rocky Creek					
Demo rail:		Demo Post:		End Anchor:		
Length of new rail:		Post at:		Curved Rail:		Radius:
Straighten rail:				Reset Posts:		Blocks:
New Posts:				Type 12A Anchor:		Type 1
New Absorber end:						
Mobilization:		LS				
Misc Cost:		LS				
Reflectors Needed:		(Y/N)				
Statement of Needs						
NOT WARRANTED - REMOVED						
Comments:	NOT IN CONTRACT. REPAIR BY OTHERS.					
COST:						



Macon-Bibb County Guardrail Information						10
Location:	1935 Forest Hill Road					
	Demo rail:		Demo Post:	End Anchor:		
Length of new W rail:	450	Post at:		Curved Rail:	Radius:	
Straighten rail:				Reset Posts:	Blocks:	
New Posts:			Type 12A Anchor:	1	Type 1	1
New Absorber end:						
Mobilization:	1	LS				
Misc Cost:		LS				
Reflectors Needed:		(Y/N)				
Statement of Needs						
New W beam guard rail.						
						
Comments:						
	COST:					

Macon-Bibb County Guardrail Information						11
Location:	Arkwright Rd in curve north of Arkwright Drive					
	Demo rail:		Demo Post:	End Anchor:		
Length of new rail:	200	Post at:	6.5	Curved Rail:	Radius:	
Straighten rail:				Reset Posts:	Blocks:	
New Posts:			Type 12A Anchor:		Type 1	3
New Absorber end:						
Mobilization:	1	LS				
Misc Cost:	1	LS				
Reflectors Needed:		(Y/N)				
Statement of Needs						
200' of new W beam guard rail. Misc. cost due to flagging requirement.						
						
Comments:						
	COST:					

Macon-Bibb County Guardrail Information						12
Location:	4804 Rivoli Drive, at Wesleyan Drive					
	Demo rail:		Demo Post:	End Anchor:		
Length of new W rail:	100	Post at:	6.5	Curved Rail:	Radius:	
Straighten rail:				Reset Posts:	Blocks:	
New Posts:			Type 12A Anchor:		Type 1	
New Absorber end:						
Mobilization:	1	LS				
Misc Cost:	1	LS				
Reflectors Needed:		(Y/N)				
Statement of Needs						
Remove and replace 100' of W Beam guard rail. 9' - deep posts, as needed. Misc. cost, due to flagging being required.						
						
Comments:						
	COST:					

Macon-Bibb County Guardrail Information						13
Location:	1200 Tucker Road, at Rocky Creek bridge					
	Demo rail:		Demo Post:		End Anchor:	
	Length of new rail:		Post at:		Curved Rail:	Radius:
	Straighten rail:				Reset Posts:	Blocks:
	New Posts:				Type 12A Anchor:	Type 1
	New Absorber end:					
	Mobilization:		LS			
	Misc Cost:		LS			
	Reflectors Needed:		(Y/N)			
Statement of Needs						
NOT WARRANTED - REMOVED						
Comments:	NOT IN CONTRACT. REPAIR BY OTHERS.					
	COST:					



Macon-Bibb County Guardrail Information						14
Location:	Tucker Rd over Rocky Creek, SW Quad					
	Demo rail:		Demo Post:		End Anchor:	
	Length of new rail:		Post at:		Curved Rail:	Radius:
	Straighten rail:				Reset Posts:	Blocks:
	New Posts:				Type 12A Anchor:	Type 1
	New Absorber end:					
	Mobilization:		LS			
	Misc Cost:		LS			
	Reflectors Needed:		(Y/N)			
Statement of Needs						
NOT WARRANTED - REMOVED						
Comments:	21' - T Beam, 87.5' - W Beam, Type 12A.					
	COST:					



Macon-Bibb County Guardrail Information						15
Location:	Log Cabin Dr at Rocky Creek, NW Quad					
	Demo rail:	12	Demo Pos	3	End Anchor:	
	Length of new W rail:	12	Post at:		Curved Rail:	Radius:
	Straighten rail:				Reset Posts:	4
	New Posts:				Type 12A Anchor:	Type 1
	New Absorber end:					
	Mobilization:	1	LS			
	Misc Cost:		LS			
	Reflectors Needed:		(Y/N)			
Statement of Needs						
Remove and replace 12' of damaged W Beam rail. Add a Type 12A end piece, not full length.						
Comments:						
	COST:					



Macon-Bibb County Guardrail Information						16
Location:	2820 Pineworth Road, at Lake					
	Demo rail:		Demo Post:	End Anchor:		
Length of new rail:	400	Post at:		Curved Rail:	Radius:	
Straighten rail:				Reset Posts:	Blocks:	
New Posts:			Type 12A Anchor:	1	Type 1	1
New Absorber end:						
Mobilization:	1	LS				
Misc Cost:	1	LS				
Reflectors Needed:		(Y/N)				
Statement of Needs						
NOT WARRANTED - REMOVED						
Comments:	400' -W Beam, Type 12 A, Type 1, 9' Posts.					
	COST:					



Macon-Bibb County Guardrail Information						17
Location:	1881 Forest Hill Road					
	Demo rail:		Demo Post:	End Anchor:		
Length of new W rail:	250 / 387	Post at:		Curved Rail:	Radius:	
Straighten rail:				Reset Posts:	Blocks:	
New Posts:			Type 12A Anchor:	2	Type 1	2
New Absorber end:						
Mobilization:	1	LS				
Misc Cost:	1	LS				
Reflectors Needed:		(Y/N)				
Statement of Needs						
Install W Beam guard rail, each side of the road, with Type 12 A and Type 1 on each. 250' of rail on the east side of the road, 387' on the west side. Misc cost, due to flagging being required.						
Comments:	W Beam Rails, Both Sides Of The Road.					
	COST:					



Macon-Bibb County Guardrail Information						18
Location:	6945 Colaparchee Road (at I-475)					
	Demo rail:		Demo Post:	End Anchor:		
Length of new W rail:	75.0	Post at:		Curved Rail:	Radius:	
Straighten rail:				Reset Posts:	Blocks:	
New Posts:			Type 12A Anchor:		Type 1	
New Absorber end:						
Mobilization:	1	LS				
Misc Cost:	1	LS				
Reflectors Needed:		(Y/N)				
Statement of Needs						
Replace 75' of tree damaged W Beam guard rail, on the south side of the road, west side of I-475. Reset / reattach or replace posts, as needed. Misc cost, due to flagging being required.						
Comments:						
	COST:					

